



Non-dimensioned details
according to SJ-Data
kontrola v napnutém stavu nad referenčními body C1 / C2
max.síla 200N
check in tensioned state over reference points C1/C2
(max. tension force 200N)

[illegible]