



general tolerance = GT in mm
Size range

≤ 30	> 30	> 120	> 400	> 1000
≤ 30	≤ 120	≤ 400	≤ 1000	

GT coarse

L	1	2	2	3	4
Δ	1	2	4	6	

lengths (L) and angle (\angle) = ± GT

Tolerance Symbols ISO 1101

- roundness = 1/2φ-Tol.
- straightness/flatness = GT
- ⊙ concentricity/run out = GT
- ≡ symmetry = GT
- // parallelism = GT
- ⊕ position = GT

Language:
e

-	27.8.2002	C.F.	PRODUCTION ISSUE	B15000		
Index - =>	00		VÝROBNÍ ČÍSLO			
Date	Checked	alteration	change no.	fr	Toler.	
Inspection dim.	auxiliary dim		Material:	weight:		
			BS EN10025 S355 J0	in kg		
Drawn	27.8.2002	M.B.	blank no:	6.5		
Checked			Title	Status:		
Approv.			PLATE	PROD.		
Manuf.			PLECH	Scale:		
Linde Heavy Truck Division Limited				1:2		
			Drawing number:	sheet:		
			S:	1		
			A: 1794461303	of:		
			repl.	1		
			Orig.			